## **Suzanne Steab - July 2010 Inspection Report**

K

From:

Karl Houskeeper

To:

GGalecki@archcoal.com

Date:

7/29/2010 1:19 PM

Subject:

July 2010 Inspection Report

CC:

 $ANGELANANCE @utah.gov; \ DARONHADDOCK @utah.gov; \ SUZANNESTEAB @utah.gov \\$ 

**Attachments:** Skyline July 2010.pdf

Gregg,

Attached is the July 2010 inspection report for Skyline.

Thanks,

Karl



# State of Utah

### DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER

Executive Director

#### Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Popropoptotiv	CO Process A During the N
	es Present During the Inspection:  Gregg Galecki
OGM	Karl Houskeeper

# **Inspection Report**

Permit Number:	C0070005
Inspection Type:	PARTIAL
Inspection Date:	Monday, July 12, 2010
Start Date/Time:	7/12/2010 9:30:00 AM
End Date/Time:	7/12/2010 2:00:00 PM
Last Inspection:	Wednesday, June 23, 2010

Inspector: Karl Houskeeper, Weather: Clear, Temp. 70 Deg. F. InspectionID Report Number: 2421

> Accepted by: jhelfric 7/29/2010

Permitee: CANYON FUEL COMPANY LLC Operator: CANYON FUEL COMPANY LLC

Site: SKYLINE MINE

Address: .

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

**Current Acreages** 

11,064.00	<b>Total Permitted</b>
84.25	Total Disturbed
	Phase I
	Phase II
	Phase III

Minera	ı	Owner	ehin
www		owner	SIND

**Types of Operations** 

$\checkmark$	Federal	V	Underground
V	State		Surface
	County		Loadout
$\checkmark$	Fee		Processing
$\Box$	Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

PR. Llouberger Karl Houskeeper,

**Date** 

Monday, July



Permit Number: C0070005 Inspection Type: PARTIAL

Inspection Date: Monday, July 12, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		✓	
3.	Topsoil				
4.a	Hydrologic Balance: Diversions	<b>V</b>		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments	<u> </u>		✓	
8.	Noncoal Waste				
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0070005 Inspection Type: PARTIAL

Inspection Date: Monday, July 12, 2010

Page 3 of 3

### 2. Signs and Markers

The mine identification signs are located at points of public access into the permit area. Signs contain the required information.

### 4.a Hydrologic Balance: Diversions

Large rock identified on previous inspection in the concrete lined diversion by the truck load out is still present. Rock needs to be removed to allow diversion to function as designed.

## 7. Coal Mine Waste, Refuse Piles, Impoundments

Refuse pile appeared stable. No visible hazards noted.